

Zamperla Inc.

Maintenance Bulletin

February 1990

RE: Freeze Damage Mini-Jet Center

Several Mini-Jet centers have experienced freeze damage when water has collected in the vertical rectangular tubing and frozen. Please inspect your Mini-Jet center piece for this condition. If your ride doesn't have weep holes in this area drill a 1/4" hole as shown in each rectangular tube. If there is damage to the tubing, the only recommended repair is replacement of the tube. There is no danger from swelling of the tube as long as there is no cracking present.

Swollen tubes should be replaced as soon as possible, (do not attempt to heat and straighten swollen tubes) cracked tubing must be replaced before operating the ride.

